




**ENECON** Mesogios Ltd  
Industrial Strength Solutions  
for All Your Repair & Maintenance Needs  
high performance polymer systems



Larnaca Airport  
Rain-water pumping  
station

Check valve repair



repairs@enecon.com.cy



+357 22 100043

## Where & When:

Cyprus, August 2016

## Client:

Airport facility

## Problem:

Corrosion on main body and shaft

## Challenge:

To bring back the valve in working condition



## ENECON products used:

DurAlloy

CeramAlloy CL+AC

CHEMCLAD SD







Imperfections on body were repaired  
with **DurAlloy**





First coat CeramAlloy CL+AC



Second coat CeramAlloy CL+AC  
+ CHEMCLAD SC











Internal area was coated with minimum 600 microns CeramAlloy CL+AC  
Outside surface with minimum 350 microns CHEMCLAD SC



ENECON Mesogios Ltd



[repairs@enecon.com.cy](mailto:repairs@enecon.com.cy)



+357 22 100043

